Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name:

Work Order Type: Weatherization

Audit Name: MADISON

CLIENT INFORMATION

Client Name:

Address:

Client ID:

Alt. Client ID: 16016SW-0973

AGENCY INFORMATION

Agency: SWHRA

Agency Phone: (731) 989-5111

Address: 1574 White AVE

Fax:

Henderson, TN

Email Address:

Agency Contact: Oliver, Jerry

Work Phone: Cell Phone: Email Address:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

NOTICE:

All work performed and material must meet all requirements as stated in the Southeast Weatherization Field Guide. It is the contractor's responsibility to pull all necessary permits required for the town or county where the work is being performed. No change order work shall be done until the change order has been approved and signed. If heater is required no air sealing should be done before heater is installed.

731-427-5422

Client Name: Client ID:

Work Order (Bid Form)

DOE Weatherization Assistant

Alt. Client ID: 16016SW-0973

Work Order Name:

Report Run On: 5/28/2010

Version 8.5.0 Page 1 of 4

Measures

,	Measure 1 Infilt	ration Redctn			Componen	ts		I.	nspected
C	omment								
				constants to determine the city of the latest and	Estimated		100 40000000000000000000000000000000000	Actual	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Construction Materials/Hardwar e	Seal basement door and add door knob, Seal pipes under kitchen sink, Seal hole in pantry (electicial wire)	Each	1			TANGON TO THE PARTY OF THE PART		
2	Labor	Labor	Hour						
3	Construction Materials/Hardwar e	Seal pipes,ceiling and floor in libray room closet, Seal pipes under vanity	Each	1					
4	Labor	Labor	Hour						
C	ther Detail						5 poor		
									and the second s
				Measure	Sub Total:] :	Sub Total:	
	Field Notes:								

	Measure 2 DWI omment	H Pipe Insulation			Component Estimated	ts		Actual	Inspected
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1					
2	Labor	Labor	Hour	1					
0	Other Detail	f					7 [-
L									
						-			
			,	Measure	e Sub Total:		5	Sub Total:	
	Measure 3 DWI omment	H Tank Insulation			Component	ʻs			Inspected
C	omment		Units		Estimated		Qtv	Actual	
C c # 1		Tank Insulation Description / Comment DHW Tank Insulation	<i>Units</i> Each	Qty 1	•	ts Total	Qty		Inspected
# 1	omment Material / Labor Hot Water	Description / Comment		Qty	Estimated		Qty	Actual	
# 1	omment Material / Labor Hot Water Equipment	Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated		Qty	Actual	
# 1	omment Material / Labor Hot Water Equipment Labor	Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated		Qty	Actual	
# 1	omment Material / Labor Hot Water Equipment Labor	Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated		Qty	Actual	
# 1	omment Material / Labor Hot Water Equipment Labor	Description / Comment DHW Tank Insulation	Each	Qty 1 1	Estimated			Actual	

Client Name:

Client ID: Alt. Client ID: 16016SW-0973

Work Order Name:

Report Run On: 5/28/2010

Measure 4 Attic Ins. R-30			Componen	ts A1		I	nspected
Comment							
			Estimated			Actual	****
# Material / Labor Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation Attic Insulation - Blown Cellulose - R-30	ı SqFt	2464				The state of the s	
2 Labor Labor	Hour	2464					
3 Construction Install Attic access cover Materials/Hardwar e	er Each	1	The state of the s				
4 Labor Labor	Hour						
Other Detail	J +200101-10000000000000000000000000000000	,				h	
			and the second				
		Measur	e Sub Total:			Sub Total:	
Field Notes:							1
Measure 5 CO Monitor is Needed Comment			Componen		44.44.44.44.44.44.44.44.44.44.44.44.44.		Inspected
Measure 5 CO Monitor is Needed Comment	Units	***************************************	Estimated		Qty	Actual Unit Cost	Inspected
Measure 5 CO Monitor is Needed	<i>Units</i> Each	Qty 1	-		Qty	Actual	
Measure 5 CO Monitor is Needed Comment # Material / Labor Description / Comment 1 Health and Safety CO monitor		Qty	Estimated		Qty	Actual	
Measure 5 CO Monitor is Needed Comment # Material / Labor Description / Comment 1 Health and Safety CO monitor Items	Each	Qty 1	Estimated		Qty	Actual	
Measure 5 CO Monitor is Needed Comment # Material / Labor Description / Comment 1 Health and Safety CO monitor Items 2 Labor Labor	Each	Qty 1	Estimated		Qty	Actual	
Measure 5 CO Monitor is Needed Comment # Material / Labor Description / Comment 1 Health and Safety CO monitor Items 2 Labor Labor	Each	Qty 1	Estimated		Qty	Actual	
Measure 5 CO Monitor is Needed Comment # Material / Labor Description / Comment 1 Health and Safety CO monitor Items 2 Labor Labor	Each Hour	Qty 1 1	Estimated			Actual	
Measure 5 CO Monitor is Needed Comment # Material / Labor Description / Comment 1 Health and Safety CO monitor Items 2 Labor Labor Other Detail	Hour	Qty 1 1	Estimated Unit Cost			Actual Unit Cost	

Client Name:

Client ID:

Alt. Client ID: 16016SW-0973

Work Order (Bid Form)

Work Order Name:

Report Run On: 5/28/2010

DOE Weatherization Assistant

Version 8.5.0

Page 4 of 4